



1020-XX
1020-05, 1020-30, 1020-55

NON-ACID / OUTDOOR CONDENSER COIL CLEANER & BRIGHTENER

NU-CLEAR (Base) is a highly concentrated cleaning system that removes a broad range of soils quickly and with minimum effort and easy to rinse away with water.

- ✓ Foams out stubborn deposits
- ✓ Excellent for grease contamination
- ✓ Non-flammable
- ✓ Contains no toxic petroleum or chlorinated solvents
- ✓ Biodegradable

DANGER: CORROSIVE. CAUSES SEVERE SKIN BURNS AND EYE DAMAGE. FOR PROFESSIONAL USE ONLY. KEEP OUT OF REACH OF CHILDREN. SEE SIDE PANELS FOR ADDITIONAL PRECAUTIONS.

DANGER: May be corrosive to metals. Causes severe skin burns and eye damage. Harmful if swallowed.

Keep in original container. Do not breathe mist/vapors/spray. Wash face, hands, and any exposed skin thoroughly after handling. Wear protective gloves/protective clothing/eye protection/face protection.

FIRST AID: IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF INHALED: Remove person to fresh air and keep comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER/Doctor. Store locked up. Dispose of contents and container in accordance with all local, regional, and national regulations.

Contains [CAS]: Potassium hydroxide [1310-58-3], sodium hydroxide [1310-73-2], sodium silicate [1344-09-8].



ISO 9001:2015
CERTIFIED

North American Research Corp.
519 Huffines Blvd., Lewisville, TX 75056
800.527.7520 | 972.492.1800
Fax: 972.394.6755
Web: NarcoChem.com
info@narcochem.com



DIRECTIONS FOR USE:

DO NOT USE ON INDOOR COILS. USE ONLY OUTDOORS.

TIP: Cleaning action is accelerated if condenser coil is still warm from use.

1. Read entire label & **Safety Data Sheet** before use.
2. Disconnect all power before working on equipment.
3. Protect surrounding area from over-spray.
4. Using a suitable low-pressure sprayer, dilute NU-CLEAR with water according to dilution rates below.
5. Always spray downwind with a coarse spray to avoid misting. Spray between fins using horizontal motion, working from the bottom up.
6. Wait 3 to 4 minutes until foam begins to subside and rinse completely with large amounts of water.
7. Flush sprayer completely with water after use.

DILUTION RATE:	ADD 1 PART CLEANER TO:
HEAVY DUTY CLEANING	3 - 5 PARTS WATER
MODERATE DUTY CLEANING	6 - 8 PARTS WATER
LIGHT DUTY CLEANING	UP TO 20 PARTS WATER